

Quantitative Fit Test Adapters for 3M Reusable Respirators

3M Respirator	Adapter/modification needed to fit test using CNC (condensation nuclei counter) quantitative method
3000 Series and 4000 Series	Manually probe facepiece
5000 Series and 6000 Series Half Facepiece	Fit test using the 3M™ Probed Reusable respirator Assembly 6100Q, 6200Q, or 6300Q, or 3M™ 6000 Series Half Facepiece with 601 Adapter Note: Respirator wearers must pass fit test with the same size respirator worn in the workplace.
6500 Series and 6500QL Series	3M™ Fit Test Adapter 601
7500 Series	
6000 Series Full Facepiece, 6000DIN	
FF-400 Series	
7800 Series	
HF-800 Series	3M™ Secure Click™ Quantitative Fit Test Adapter Kit HF-800-03
FF-800 Series	3M™ Secure Click™ Quantitative Fit Test Adapter Kit FF-800-06

For CNP (controlled negative pressure) fit testing, contact the quantitative fit test device manufacturer for help selecting the correct fit test adapter.

www.ohdglobal.com



Personal Safety Division
3M Center
Building 235-2W-70
St. Paul, MN 55144-1000

3M PSD products are occupational use only.

3M Canada
P.O. Box 5757
London, Ontario
N6A 4T1

In United States of America
Technical Service:
Customer Service:
3M.com/workersafety

1-800-243-4630
1-800-328-1667

In Canada

Technical Service: 1-800-267-4414
Customer Service: 1-800-364-3577
3M.ca/Safety

© 2025, 3M. All rights reserved.
3M is a trademark of 3M. Used under license in Canada. All other trademarks are property of their respective owners.